

# TECHNICAL SERVICE BULLETIN

**TB09-121R**

**TO: RESIDENTIAL DISTRIBUTORS**  
**FROM: TECHNICAL SERVICE DEPARTMENT**  
**DATE: JUNE 18, 2009**  
**RE: Condensate Pressure Switch in \*G7SL, and \*GC2SL**

Nordyne is pleased to announce a change in the above listed Downflow furnaces. In an effort to enhance the performance of the single stage 92+ Downflow furnaces, the pressure switch that connects to the condensate pan has been removed. Furnaces that have two pressure switches do not need to be modified. If a furnace is cycling on the condensate pressure switch, it is acceptable to remove that switch from the furnace.

It is necessary to check and verify the negative pressure that the induced draft motor is producing against the pressure switch setting, the integrity of the inducer orifice, any air leaks at gaskets or tubing, breached heat exchanger(s), restricted flue(s) or any situation that would affect the negative pressure sensed by the switch.

If you have any questions please call Nordyne Technical Service Department at 1-800-422-4328 ext. 2.

NORDYNE  
Technical Service Department



*Frigidaire*



**BRAN**  
HEATING AND COOLING SYSTEMS

**TAPPAN**

NuTone

**Kelvinator**  
Heating and Cooling Products

**PHILCO**  
Heating and Cooling Products

**Gibson**  
Heating and Cooling Products

**GRANDAIRE**

