

TECHNICAL SERVICE BULLETIN

TB08- 120R

TO: RESIDENTIAL AND MAYTAG DISTRIBUTORS
RESIDENTIAL AND MAYTAG DEALERS
FROM: TECHNICAL SERVICE DEPARTMENT
DATE: MAY 2008
RE: Gas line interference with the Pressure switch on the G7/MGC2 Furnaces

It has come to the attention of Nordyne there is an issue where the pressure switch can interfere when the gas line is installed.

When installing the gas line in the G7/MGC2 furnace, it is necessary to remove the pressure switch that is located on the inducer motor. If the pressure switch is left in place, it can become damaged. The switch should be removed by removing the 2 screws that attach the switch to the housing, install the gas pipe, and then re-attach the pressure switch in the same location.

All pressure switches in production have been relocated to prevent any interference issues in the future.



Remove the pressure switch prior to installing the gas line. Reinstall the pressure switch after the gas line is installed.



If you have any questions please contact Nordyne Technical Service at 1-800-422-4328. Ext. 2.

Nordyne Technical Service



