

TECHNICAL SERVICE BULLETIN

TB09-135R

TO: RESIDENTIAL DISTRIBUTORS
FROM: TECHNICAL SERVICE DEPARTMENT
DATE: JULY 7, 2009
RE: C6 FLEX COIL REMINDERS

Nordyne has received calls regarding the installation of a piston in the C6 flex coil. A piston **cannot** be installed in a C6 flex coil.

With the C6 flex coil you can install either an R-22 TXV or 410a TXV depending on the application. Below are the kit numbers for the C6 Flex coil.

TXV Kits

920662	R-22 2.0T
920663	R-22 2.5T
920664	R-22 3.0T
920665	R-22 3.5T
920666	R-22 4.0T
920667	R-22 5.0T
920668	R-410a 2.0T
920669	R-410a 2.5T
920670	R-410a 3.0T
920671	R-410a 3.5T
920672	R-410a 4.0T
920673	R-410a 5.0T

If you have any questions please call Nordyne Technical Service Department at 1-800-422-4328 ext. 2.

NORDYNE
Technical Service Department



Frigidaire



BRAN
HEATING AND COOLING SYSTEMS

TAPPAN

NuTone

Kelvinator
Heating and Cooling Products

PHILCO
Heating and Cooling Products

Gibson
Heating and Cooling Products

GRANDAIRE