

TB09-139R

TECHNICAL SERVICES BULLETIN

To: Residential Distributors
From: Technical Service Department
Date: JULY 30, 1009
Re: CORRECT SENSOR PART NUMBER

Bulletin TB09-137 incorrectly listed the sensor part number for the Modulating Gas Furnace with a Conventional Heat Pump.

The correct part number for the sensor needed for the Modulating Gas furnace with Conventional Heat Pump is **920938**.

If you have any questions please contact NORDYNE Technical Service at 1-800-422-4328.

Thank You
Nordyne Technical Service