

TB10-105R

TECHNICAL SERVICES BULLETIN

To: Residential Distributors and Dealers

From: Technical Support

Date: January 20, 2010

Re: Rollout Limit Change in the *G7SC/MGC2SC-120D-45D

Nordyne is pleased to announce a change in the rollout limit setting in the *G7SC/MGC2SC120D-45D. Nordyne will replace the (62654) 160°F Roll out limit to the (626558) 185°F rollout limit.

If you have any questions please call **1-800-422-4328 ext. 2**

Thanks You

Nordyne Technical Service