

To: Residential Distributors and Dealers
From: Technical Support
Date: February 4, 2010
Re: Missing Sensor in iQ Replacement Sensor Kit (624678)

NORDYNE is aware of missing coil sensors **(624678)**, sold as replacement parts.



Some of the replacement sensors packages only included the extension wires and not the sensor.

If you received one of these sensors kits, missing the sensor, please return the sensor kit using the RGA process.

Thank You
NORDYNE Technical Service