


RPB09-159 PRODUCT BULLETIN

TO: Residential Distributors
FROM: Jeff Gamache
DATE: 8/25/09
RE: GB5BM-0 R-410A Piston Change

ROUTE TO:	✓ SEEN	No. of Copies Distributed

NORDYNE is pleased to announce a running change in the GB5BM-0 Piston Air Handlers. Beginning in late August Nordyne production is converting to the utilization of an R-410A Piston; current production models utilize an R22 piston. The change was driven to allow easier field matches to 13 SEER R-410A Heat Pumps. The only AHRI ratings that currently utilize a piston are 13 SEER R-410A Heat Pumps with Piston Air Handlers. The change can be noted on the rating plate label and we have added pink stickers to both the coil and carton labels to designate the R-410A piston change (Please see images below).

In addition to the piston change, Nordyne is also pleased to announce improved TXV installation with GB5BM-0 Air Handlers. Simultaneously with the piston change; Nordyne has begun including an additional liquid line assembly in the coil area to allow easier field TXV kit installation. If a TXV kit is utilized the additional liquid line assembly allows the installer to align the liquid line to the door. If a TXV kit is not utilized the additional liquid line assembly is not required.



If you have any questions or require further assistance, please contact your RSM.