

To: Residential Distributors

From: Technical Service Department

Date: August 24, 2009

Re: Removal of the Blower Deck Limit in *G7SK (MGC2SK), *G7TK (PGC2TK or MGC2TK).

Nordyne recently removed the blower deck limits from the following Downflow units, *G7SK (MGC2SK), *G7TK (PGC2TK or MGC2TK).

Any units produced the before the following serial number will include the blower deck limits, and any units produced after the serial number and including the following serial number will not have the blower deck limits. The furnace will continue to have two limits on the side of the blower housing.

FGD090801631.

If you have any questions please call Nordyne Technical Service at 1-800-422-4328 ext.2.

Nordyne Technical Service