

TB09-155R

TECHNICAL SERVICES BULLETIN

TO: Residential Distributors and Dealers
From: Technical Service Department
Date: November 10, 2009
Re: *G7/*GC2 Burner Assembly Changes

NORDYNE is pleased to announce continuing improvements to the *G7/*GC2 gas furnace product. All NORDYNE brands have been upgraded to a silicone nitride igniter. The product will be further enhanced with the removal of the igniter bracket. The silicone nitride igniter will mount directly into the burner box.

The replacement igniter kit 921074-0 will include an igniter and a mounting bracket for furnace equipped with a silicone carbide igniter.

If you have any questions please contact NORDYNE Technical Services at 1-800-422-4328 ext 2

Thank You,
Nordyne Technical Service

